## Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: Whiting Oil and Gas Corporation
Well Name/Number: Iverson Bros 31-1-1H

Location: (NW NE) Lot 2 Section 1 T25N R57E

County: Richland, MT; Field (or Wildcat) W/C (Bakken Horizontal)
Air Quality
(possible concerns)
Long drilling time: No. 20 to 30 days drilling time.
Unusually deep drilling (high horsepower rig): No, triple derrick drilling rig to drill a single lateral Bakken Formation well, 21,386'MD/10,399'TVD.
Possible H2S gas production: Yes possible H2S gas, slight chance from Mississippian
Formations.
In/near Class I air quality area: No Class I air quality area in the area of review.
Air quality permit for flaring/venting (if productive) Yes, DEQ air quality permit required
under rule 75-2-211.
<u></u>
Mitigation:
Air quality permit (AQB review)
Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: No special concerns – using triple derrick drilling rig to drill a single
lateral horizontal Bakken Formation well, 21,386'MD/10,399'TVD. If existing gas
gathering system for natural gas in the area, associated gas can be gathered or if no
gathering system nearby, associated gas can be flared under Board Rule 36.22.1220.
Water Quality
(possible concerns)
Salt/oil based mud: Yes, oil based invert mud system will be used for drilling the
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral.
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.  Water well contamination: None, closest water wells are about 5/8 of a mile to the north
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.  Water well contamination: None, closest water wells are about 5/8 of a mile to the north northwest, and about 5/8 of a mile to the west from this location. Depth of these stock
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.  Water well contamination: None, closest water wells are about 5/8 of a mile to the north northwest, and about 5/8 of a mile to the west from this location. Depth of these stock water wells range from 90' to 120'. Surface hole will be drilled with freshwater and
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.  Water well contamination: None, closest water wells are about 5/8 of a mile to the north northwest, and about 5/8 of a mile to the west from this location. Depth of these stock
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.  Water well contamination: None, closest water wells are about 5/8 of a mile to the north northwest, and about 5/8 of a mile to the west from this location. Depth of these stock water wells range from 90' to 120'. Surface hole will be drilled with freshwater and freshwater mud to 2000', rule 36.22.1001. Steel surface casing will be run and
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.  Water well contamination: None, closest water wells are about 5/8 of a mile to the north northwest, and about 5/8 of a mile to the west from this location. Depth of these stock water wells range from 90' to 120'. Surface hole will be drilled with freshwater and freshwater mud to 2000', rule 36.22.1001. Steel surface casing will be run and cemented from 2000' to surface.
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.  Water well contamination: None, closest water wells are about 5/8 of a mile to the north northwest, and about 5/8 of a mile to the west from this location. Depth of these stock water wells range from 90' to 120'. Surface hole will be drilled with freshwater and freshwater mud to 2000', rule 36.22.1001. Steel surface casing will be run and cemented from 2000' to surface.  Porous/permeable soils: No, sandy silty clay soils.  Class I stream drainage: No Class I stream drainages in the area of review.
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.  Water well contamination: None, closest water wells are about 5/8 of a mile to the north northwest, and about 5/8 of a mile to the west from this location. Depth of these stock water wells range from 90' to 120'. Surface hole will be drilled with freshwater and freshwater mud to 2000', rule 36.22.1001. Steel surface casing will be run and cemented from 2000' to surface.  Porous/permeable soils: No, sandy silty clay soils.  Class I stream drainage: No Class I stream drainages in the area of review.  Mitigation:
mainhole (oil/water ratio 70/30 invert mud) and saltwater for drilling the horizontal lateral. Freshwater and freshwater mud system will be used for drilling the surface hole, Rule 36.22.1001.  High water table: No, high water table at this well location.  Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributaries to Otis Creek, about 3/8 of a mile to the northeast and about 5/16 of a mile to the southeast from this location. Within in Otis Creek there is a stock pond, about 2.25 miles to the northeast from this location.  Water well contamination: None, closest water wells are about 5/8 of a mile to the north northwest, and about 5/8 of a mile to the west from this location. Depth of these stock water wells range from 90' to 120'. Surface hole will be drilled with freshwater and freshwater mud to 2000', rule 36.22.1001. Steel surface casing will be run and cemented from 2000' to surface.  Porous/permeable soils: No, sandy silty clay soils.  Class I stream drainage: No Class I stream drainages in the area of review.

Other:
Comments: Adequate surface casing and operational BOP equipment should
mitigate any problems. (BOP's 5,000 psig annular, pipe and blind rams) rule
36.22.1014. No concerns.
Wildlife/recreation
(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): None identified.
Proximity to recreation sites: None identified
Creation of new access to wildlife habitat: No
Conflict with game range/refuge management: No
Threatened or endangered Species: Species identified as threatened or endangered
are the Pallid Sturgeon, Interior Least Tern, Whooping Crane and Piping Plover.
Candidate species are the Greater Sage Grouse and the Sprague's Pipit. MTFWP
Natural Heritage Tracker website indicates one (1) species of concern is the Whooping
<u>Crane.</u>
Mitigation:
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DSL)
Screening/fencing of pits, drillsite
Other:
Comments: Private cultivated surface lands. There may be species of concern
that maybe impacted by this wellsite. We ask the operator to consult with the surface
owner as to what he would like done, if a species of concern is discovered at this
location. The Board of Oil & Gas has no jurisdiction over private surface lands.
Historical/Cultural/Paleontological
(possible concerns)
Proximity to known sites None identified.
Mitigation
avoidance (topographic tolerance, location exception)
other agency review (SHPO, DSL, federal agencies)
Other: Comments:Private cultivated surface lands. There may be possible
historical/cultural/paleontological sites that maybe impacted by this wellsite. We ask the
operator to consult with the surface owner as to his desires to preserve these sites or
not, if they are found during construction of the wellsite. The Board of Oil & Gas has no
jurisdiction over private surface lands.
Social/Economic
(possible concerns) Substantial effect on tax base
Substantial effect of tax base Create demand for new governmental services
Population increase or relocation
Comments: Wildcat well, no concerns.

## Remarks or Special Concerns for this site

Whiting Oil and Gas to drill a wildcat single lateral horizontal Bakken Formation well, 21,386'MD/10,399'TVD.

## **Summary: Evaluation of Impacts and Cumulative effects**

No significant long term impacts expected, some short term impacts will occur.
I conclude that the approval of the subject Notice of Intent to Drill (does/ <u>does not</u> ) constitute a major action of state government significantly affecting the quality of the human environment, and (does/ <u>does not</u> ) require the preparation of an environmental impact statement.
Prepared by (BOGC): /s/Steven Sasaki (title:) Chief Field Inspector Date: March 21, 2013
Other Persons Contacted:
Montana Bureau of Mines and Geology, GWIC website (Name and Agency) Water wells in Richland County (subject discussed) March 21, 2013 (date)
US Fish and Wildlife, Region 6 website (Name and Agency) ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA COUNTIES, Richland County (subject discussed)
March 21, 2013 (date)
Montana Natural Heritage Program Website (FWP) (Name and Agency) Heritage State Rank= S1, S2, S3, T25N R57E (subject discussed)
March 21, 2013 (date)
Montana Cadastral Website (Name and Agency) Surface Ownership and surface use Section 1 T25N R57E (subject discussed)

March 21, 2013
(date)
If location was inspected before permit approval:
Inspection date:
Others present during inspection: